

## Under Review Notification

**Raised By:** David Bain

**Product #:** D206-642-149/-151/-249/-251

**Date:** 13.10.04

**Product Name:** Wearplate Assy

Part Number	Drawing/Document	"Y" or "N" Required								Instructions
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise customers	Stop Production	Re-Work Stock	IPP Under Review	Blue File Under Review	ECN # Required	
D3805-041	D3805 Rev B	y	y	n	y	y	y	y	653	Replace Gasket (D3807) w/Rockgard
D3805-043	D3805 Rev B	y	y	n	y	y	y	y	653	Replace Gasket (D3807) w/Rockgard
D3805-045	D3805 Rev B	y	y	n	y	y	y	y	653	Replace Gasket (D3807) w/Rockgard
D3805-047	D3805 Rev B	y	y	n	y	y	y	y	653	Replace Gasket (D3807) w/Rockgard

**Description of issue:**  
 Ft Rucker wants the rubber gasket replaced by a paint on coating of Rockgard. Drawing to be revised to Rev C (remove D3807-1/-3/-5/-7 Gasket, Revise Note 11, Sheet 2 (remove gasket/adhesive note, add Rockgard instruction))

**Distribution:**

General Manager	Chief Engineer
Production Manager	Engineering Project Managers
Director Quality Assurance	Engineering Clerk
Design Manager	Marketing